## Table 4-1

# Action Levels Range 4A Fog Oil Storage Area Pelham Range, Parcel 123(6) Fort McClellan, Calhoun County, Alabama

(Page 1 of 2)

When in Level C Personal Protective Equipment (PPE)

| Analyte                             | Action Level   | Required Action <sup>a</sup>  |
|-------------------------------------|--|---|
| Volatile Organic<br>Compounds (VOC) | ≥ 10 parts per million (ppm) above background in breathing zone (BZ) | Stop work, evacuate work area, notify CIH.  |
| Oxygen                              | ≥ 20%, ≤23%<br>< 20%, >23%   | Normal operations. Stop work, evacuate work area/notify CIH.                      |
| Flammable vapors                    | ≥ 10% lower explosive limit (LEL) < 10% LEL                          | Stop work, evacuate work area, notify CIH. Continue operations, monitor for VOC's |
| Benzene                             | ≥ 5 ppm in BZ  | Notify CIH, stop work, evacuate work area.  |

### When in Level D Modified/D PPE

| Analyte          | Action Level                   | Required Action <sup>b</sup>   |
|------------------|--------------------------------|--|
| VOCs             | ≥ 5 ppm above background in BZ | Stop activities, suspend work activities for 15 to 30 minutes, if readings are sustained then upgrade to Level C PPE/notify CIH.  Check benzene using detector |
|                  |                                | tube, if > 1.0 ppm, notify CIH.  |
| Oxygen           | ≥ 20%, ≤23%<br>< 20%, >23%     | Normal operations. Stop work, evacuate work area/notify CIH.   |
| Flammable vapors | ≥ 10% LEL < 10% LEL            | Stop work, evacuate work area/notify CIH. Continue operations, monitor for VOCs.   |
| Benzene          | ≥ 1 ppm in BZ                  | Notify CIH; upgrade to Level C PPE.  |

#### Table 4-1

# **Action Levels** Range 4A Fog Oil Storage Area Pelham Range, Parcel 123(6) Fort McClellan, Calhoun County, Alabama

(Page 2 of 2)

#### When in Support Zone

| Analyte | Action Level                   | Required Action  |
|---------|--------------------------------|--|
| VOCs    | ≥ 1 ppm above background in BZ | Evacuate support zone and reestablish perimeter of exclusion zone. |

No one is permitted to downgrade levels of PPE without authorization from the H&S manager.

<sup>&</sup>lt;sup>a</sup> Four instantaneous peaks in any 15-minute period or a sustained reading for 5 minutes in excess of the

action level will trigger a response.

b Contact with the H&S manager must be made prior to continuance of work. The H&S manager may then initiate integrated air sampling along with additional engineering controls.